

N. Labeling and Signage

1. All areas where radioactive materials are used or stored shall be conspicuously posted with a standard "[Caution – Radioactive Materials](#)" sign.
2. In all areas where radioactive materials are used, Radiation Safety will post [Form NRC-3, "Notice to Employees,"](#) and a notice indicating the location for inspection of the following:
 - a. NRC regulations
 - b. NRC license
 - c. All correspondence relating to the license
3. Radiation caution signs or labels will be attached to all fume hoods, containers, and other equipment that contain or are contaminated with radioactive materials. These signs will have the following information printed on them:
 - a. The radiation caution symbol
 - b. The words "Caution-Radioactive Materials"
4. Hot rooms are used exclusively for work involving radioactive materials and will be posted with an additional [hot room designation sign](#).
5. At the discretion of the RSO, additional items such as barricades, ropes, and painted warning lines may be required.